



Części niezbędne do skonstruowania oprawy na bazie profilu GIZA-LL



Profil (A) Zaślepka (B) Osłona (C) Taśma LED (D) Sprężyna (E) Uszczelka (F)


Elementy niezbędne przy czynnościach montażowych:

- wiertarka


UWAGA! Wszystkie taśmy LED powinny być podłączone do zasilacza 12 V lub 24 V.

WAŻNE: Instrukcja przedstawia podstawową formę montażu.
Więcej metod i powiązanych akcesoriów znajdziesz na stronie


1. Wywierć otwory (min. Ø 10 mm) na zamocowanie profilu.




2. Włóż sprężynę (E) w uszczelkę (E).




3. Wklej taśmę LED (D), wyprowadź przewód i załóż osłonę (C) .
Przewód może być wyprowadzony przez otwór nawiercony w profilu lub w zaślepce.




4. Wsuń Sprężynę (E) w profil (A) a następnie wsuń zaślepkę (B).



5. Podłącz zasilanie i wsuń profil (A).





Parts needed to mount the GIZA-LL extrusion



Extrusion (A)



End cap (B)



Cover (C)

LED strip (D)



Spring (E)



Isolating base (F)


Tools needed for mounting:

- drill


NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure.
More mounting procedures and related accessories can be found


1. Drill holes (min. ø 10 mm) to mount the extrusion.




2. Insert the spring (E) into the isolating base (F).



3. Mount the LED strip (D), lead out the cable and insert the cover (C) The cable may run through a hole drilled in the extrusion or one in the end cap.



4. Insert the spring (E) into the extrusion (A). Insert the end cap (B).



5. Connect power and insert the extrusion (A).

