



Części niezbędne do użycia PUSZKI HERMETYCZNEJ




Elementy niezbędne przy czynnościach montażowych:


- śrubokręt
- klucz płaski (19)

UWAGA! Lista produktów, z którymi współpracują wybrane akcesoria dostępna jest na stronie


1. Wprowadź przewody Fi 6-9 mm przez nakrętki dociskające (A) do korpusu puszki (B). Zalecamy uzycie kabla typu YvKSLY.




2. Połącz przewody np. przy użyciu kostki elektrycznej i umieść miejsce łączenia wewnątrz korpusu.




3. Dokręć nakrętki dociskające przy użyci u klucza płaskiego.




4. Załóż nakrętkę (C) na korpus.





Parts needed to assemble the WATERPROOF SPLITTER




Tools needed for mounting:


- screwdriver
- flat wrench (19)

NOTE! A list of products corresponding with the selected accessories is available


1. Run the cables with a diameter of 6-9 mm through the plastic nuts (A) into the body of the splitter (B). We recommend using a YvKSLY cable.



2. Connect the cables using e.g. a connection block and place the connection inside the body.



3. Tighten the plastic nuts with the flat wrench.



4. Put the lid (C) on the body and twist it shut

